

ਵੱਲੋਂ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸਾਖਾ,
ਸੰਗਰੂਰ।

ਵੱਲੋਂ

ਪ੍ਰਿੰਸੀਪਲ,
ਡਾ. ਗਗਨਦੀਪ ਰੋਟਰੀ ਪਬਲਿਕ ਸਕੂਲ,
ਸੁਨਾਮ।

ਨੰਬਰ: 14


ਮਿਤੀ: 13/04/2026

ਵਿਸ਼ਾ:- ਸਾਲ 2026-27 ਦੇ ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਪ੍ਰਾਪਤ ਹੋਇਆ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਦਾ ਕੇਸ ਸਬੰਧਿਤ ਜੇ.ਈ. ਵੱਲੋਂ ਮਿਤੀ: 02.04.2026 ਨੂੰ ਸਕੂਲ ਦੀ ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਕਰਨ ਉਪਰੰਤ ਕੀਤੀ ਗਈ ਰਿਪੋਰਟ ਅਨੁਸਾਰ ਸਾਲ 2026-27 ਬਿਲਡਿੰਗ ਸਰਟੀਫਿਕੇਟ ਆਪ ਜੀ ਨੂੰ ਅਗਲੇਰੀ ਯੋਗ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ। ਲੋੜੀਂਦੀ ਇੰਨਸਪੈਕਸ਼ਨ ਫੀਸ ਆਪ ਵੱਲੋਂ ਆਨਲਾਇਨ ਖਜਾਨੇ (Head of Account 8782-00-102-01-00) ਵਿੱਚ ਬਾਬਤ ਰੁਪਏ 10,000/- (ਦੱਸ ਹਜ਼ਾਰ ਰੁਪਏ ਸਿਰਫ) Receipt. No.22864929 ਮਿਤੀ: 13.04.2026 ਰਾਹੀਂ ਜਮ ਕਰਵਾ ਦਿੱਤੀ ਗਈ ਹੈ।

ਇਸ ਤੋਂ ਇਲਾਵਾ ਆਪ ਵੱਲੋਂ ਨਾਲ ਨੱਥੀ ਕੀਤਾ ਗਿਆ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ, ਜਿਸ ਦੀ ਜਾਰੀ ਕਰਨ ਦੀ ਮਿਤੀ: 22/05/2025 ਹੈ, ਦੇ ਸਬੰਧ ਵਿੱਚ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਉਕਤ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਦੇ ਮਿਆਦ 31/03/2027 ਤੱਕ ਵਧਾਉਣ ਦੀ ਜ਼ਿੰਮੇਵਾਰੀ ਆਪ ਦੀ ਨਿੱਜੀ ਹੋਵੇਗੀ ਅਤੇ ਮਿਆਦ ਵਧਾਉਣ ਉਪਰੰਤ ਇਹ ਦਫਤਰ ਨੂੰ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਜਿਹਾ ਨਾ ਕਰਨ ਦੀ ਸੂਰਤ ਵਿੱਚ ਇਸ ਦਫਤਰ ਵੱਲੋਂ ਜਾਰੀ ਕੀਤਾ ਗਿਆ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ: 22/05/2026 ਤੋਂ ਬਾਅਦ ਰੱਦ ਸਮਝਿਆ ਜਾਵੇਗਾ।


ਨੱਥੀ:- ਸਰਟੀਫਿਕੇਟ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸਾਖਾ,
ਸੰਗਰੂਰ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾੰਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸਾਖਾ ਸੰਗਰੂਰ ਜੀ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ.21451 ਮਿਤੀ:24.03.2026 ਦੇ ਸਬੰਧ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ.2 ਭ ਤੇ ਮ ਸਾਖਾ


Part-II


Building Safety Report

Name of School: Dr. Gagandeep Rotary Public School, SUNAM

Sh. Satnam Singh (Junior Engineer) has visited the above mentioned school on dated 02/04/2026 and on his visual inspection; the building seems to be safe subject to the following observation & conditions.

- a) Parameters to check the stability and safety of building as Architectural Drawings, Bearing capacity, Foundation detail, Structural Drawings, Technical Specifications, Test Reports of Material used, Quality Control reports and certificate from the Engineer in-Charge for construction are not available.
- b) In case any addition, alteration or expansion and modification to this building are done certificate may be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is any settlement of walls/ foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check stability and safety of the building.
- d) This Certificate holds validity with valid Fire Safety Certificate. A separate certificate regarding Fire Fighting should be obtained from the competent Authority. **It will be your personal responsibility to extend the period of the said fire safety certificate upto 31/03/2027 and after extending the period, this office should be informed , failing which the building safety certificate issued by this office will be considered cancelled with immediate effect.**
- e) A separate certificate regarding Electrical works should be obtained from the competent Authority.
- f) The owner of the building / Management is fully responsible regarding safety of the building from all angles in spite of the report.
- g) The covered area of the building is As per Drawings Sft.
- h) The report is not valid for legal purpose.
- i) The building visually seems safe to occupy for normal use to **One Year, upto 31.03.2027**


(Satnam Singh)
J.E


Sub Divisional Engineer
Const. Sub Divn.No.2 PWD, B&R
Sangrur.